DEPARTMENT OF TRANSPORTATION


## **REPORT OF BRIDGE SURVEY**

U.S. COAST GUARD CG-2541-D11 (Rev2/99)

INSTRUCTIONS: 1. Submit this report to the Auxiliary Coordinator as soon as possible after conducting the survey.

- 2. The best time to survey bridges is shortly betore sunset so you can observe any hazards or discrepancies before dark, then observe the lights after dark.
- 3. If conducting the survey by land, respect all property rights. DO NOT TRESPASS.
- 4. Auxiliarists do not have law enforcement authority. Take care that your survey is not interpreted as a law enforcement action.
- 5. Minor discrepancies (e.g. one light out, clearance gauges hard to read) should be reported by mail.

More serious problems (e.g. most or all lights out, hazards to navigation, bridge malfunction) should be reported to the nearest Coast Guard Group Office by telephone or radiotelephone. If in doubt, report it.						
NAME OF BRIDGE				LATI	TUDE	LONGITUDE
SPRR BRIDGE				,	36 58.1' N	122 00.1' W
NAME OF WATERWAY				MILE	S ABOVE MOUTH	TYPE OF BRIDGE
WOODS LAGOON					0.6	F
NAME/ADRESS OF BRIDGE OWNER				NAME/ADDRESS OF BRIDGE OPERATOR (if different)		
Southern Pacific Lines				Santa Cruz Harbormaster		
1 Market Street				135 Fifth Street		
San Francisco	cisco CA 94105			Santa Cruz <u>CA</u> 95060		
Fill out the section below and annotate the diagram on the reverse. Show north arrow or direction of current.						
TYPE OF LIGHTS	Number of Lights	Are Lights Correctly Placed?	Are Ligh of Prop Color/A	er	Are Lights Visible for 1 Naut. Mi?	State Condition of Lights
Channel Center Lights	4					
Margin of Channel Lights	0					
Pier Lights	6					
Pier Axis Lights	0					
Movable Span Lights	0					
Preferred Channel Lights	0					
OTHER FEATURES	How Many?	LLNR	Characteristic		Range	Working Properly?
Fog Signals	0	0	N/A	4	N/A	
Raco ns	0	0	N/A	4	N/A	
Condition of fenders: Condition of vertical clearance gauges:						
Is the bridge name shown? What name is shown?						Is sign visible to mariners?
Are navigational clearances impaired by disrepair, cables, etc? Are nav. clearances impaired by accumulation of debris?						
Is there any equipment (e.g. barges, scaffolds) in the navigation spans that is not listed in the LNM/BNM?						
If a drawbridge, is it capable of operating?  Are the operating regulations posted?						Discrepant
Is there evidence of bridge or fender damage that might be from vessels?						Watching properly
Date and Time of Survey  Name and Member Number						Home Telephone Number
Signature of Surveyor						Aux. File Number 47



Comments: Due to the proximity of these bridges, lighting for both bridges are included on one diagram.

eliterature de la companya de la co

A CANADA CANADA

referribles to all segue

matricipies marketicis

karringa kan ini manggalangan mengangan pengangan kan pengangan pengangan pengangan pengangan pengangan pengan Tinggalangan mengangan pengangan pengangan pengangan pengangan pengangan pengangan pengangan pengangan pengang

The territory of the first of the first of the first of the territory of the product independency of the territory

The Same Bertales, the south for the Same Continue Continue and the Continue and the Same Continue and the Sam

El división la la como